

Appendix M

Planned Life-cycle Asset Replacement (PLAR) Projects Completed Summer 2016

	Facility	Project Scope		Facility	Project Scope
1	Argyle MS	Lockers	60	Gaithersburg MS	Tennis Court Renovation
2	Argyle MS	Gym Floor (Refinishing)	61	Gaithersburg MS	Walk-In-Cooler & Freezer
3	Argyle MS	Paint (Interior & Exterior)	62	Galway ES	PA System
4	Ashburton ES	Paint (Interior & Exterior)	63	Georgian Forest ES	Paint (Interior & Exterior)
5	John T. Baker MS	Library Security Gate	64	Germantown ES	Playground Equipment
6	John T. Baker MS	Suspended Ceilings and Lights	65	Germantown ES	Suspended Ceilings and Lights (Phase 1 of 2)
7	Benjamin Banneker MS	Suspended Ceilings and Lights (Phase 2 of 2)	66	Greencastle ES	Concrete
8	Bannockburn ES	Gym Floor (Line Painting)	67	Greenwood ES	PA System
9	Bannockburn ES	Playground Equipment	68	Highland View ES	Exterior Wall Repairs
10	Lucy V. Barnsley ES	Paint Exterior Doors	69	Highland View ES	Paint (Interior & Exterior)
11	Bethesda-Chevy Chase HS	Stage Curtain	70	Walter Johnson HS	Concrete
12	Bethesda ES	Gym Floor Replacement	71	John F. Kennedy HS	Gym Floor (Aux)
13	Bethesda ES	Playground Equipment (Pre-K)	72	John F. Kennedy HS	Stair Treads
14	Montgomery Blair HS	HVAC Parts	73	Martin Luther King, Jr. MS	Gas Water Heater
15	Montgomery Blair HS	Running Track	74	Kingsview MS	Gas Water Heater
16	James Blake HS	Running Track	75	Lakewood ES	Playground Equipment
17	Briggs Chaney MS	Won-Door Fire Doors	76	Laytonsville ES	Emergency Generator
18	Briggs Chaney MS	Concrete	77	JoAnn Leleck ES	Restroom Repairs
19	Brooke Grove ES	Playground Equipment	78	Luxmanor ES	Restroom Repairs
20	Brooke Grove ES	Asphalt	79	Col. Zadok Magruder HS	Restroom Repairs
21	Brooke Grove ES	Dielectric Unions	80	Col. Zadok Magruder HS	Door Replacement Phase 1
22	Brooke Grove ES	Line Painting	81	Col. Zadok Magruder HS	Line Painting
23	Burnt Mills ES	Restroom Repairs	82	Thurgood Marshall ES	Exterior Wall Repairs
24	Cabin John MS	Wire Mesh Panels	83	Thurgood Marshall ES	Paint (Interior & Exterior)
25	Chevy Chase ES	Waterproofing	84	Maryvale ES	Restroom Repairs
26	Winston Churchill HS	Running Track	85	Maryvale ES	Playground Equipment
27	Winston Churchill HS	Water Heater	86	Spark M. Matsunaga ES	Playground Equipment
28	Clarksburg ES	Paint (Interior & Exterior)	87	S. Christa McAuliffe ES	Boiler Replacement
29	Clarksburg HS	Running Track	88	S. Christa McAuliffe ES	Chiller/Cooling Tower Replacement
30	Clearspring ES	Concrete	89	Ronald McNair ES	Gas Water Heater
31	Roberto Clemente MS	Windows	90	Meadow Hall ES	Paint (Interior & Exterior)
32	Roberto Clemente MS	Lockers	91	Mill Creek Towne ES	Playground Equipment
33	Cloverly ES	Emergency Generator	92	Monocacy ES	Playground Equipment
34	Captain James Daly ES	Concrete	93	Richard Montgomery HS	Line Painting
35	Captain James Daly ES	Playground Equipment	94	Neelsville MS	Emergency Generator
36	Damascus HS	Paint	95	Neelsville MS	Tennis Court Renovations
37	Damascus HS	Auditorium Stage Floor	96	New Hampshire Estates ES	Casework & Sinks (Classrooms)
38	Damascus HS	Ceiling Repairs & Painting	97	New Hampshire Estates ES	Emergency Generator
39	Damascus HS	Gym Floor	98	Northwest HS	Gas Water Heater
40	DuFief ES	Restroom Repairs	99	Northwest HS	Floor Covering
41	East Silver Spring ES	Floor AP Room	100	Northwest HS	Gym Floor Refinishing (Aux)
42	Eastern MS	Restroom Repairs	101	Northwood HS	Folding Partition Aux Gym
43	Albert Einstein HS	Floor Repairs	102	Oakland Terrace ES	Asphalt
44	Albert Einstein HS	Gym Floor (Aux)	103	Oakland Terrace ES	Exterior Wall Repairs
45	Albert Einstein HS	Line Painting	104	Oakland Terrace ES	Line Painting
46	Albert Einstein HS	Windows	105	Oakland Terrace ES	Paint (Interior & Exterior)
47	Fallsmead ES	Restroom Repairs	106	Olney ES	Floor Covering
48	William H. Farquhar MS	Restroom Repairs	107	William T. Page ES	Playground Equipment
49	Flower Valley ES	Fire Alarm Panel Upgrade	108	Paint Branch HS	Line Painting
50	Forest Knolls ES	Playground Equipment	109	Piney Branch ES	PA System
51	Forest Knolls ES	Paint (Interior & Exterior)	110	Poolesville HS	Restroom Repairs
52	Fox Chapel ES	Restroom Repairs	111	Potomac ES	Restroom Repairs
53	Robert Frost MS	Restroom Repairs	112	Potomac ES	Water Heater
54	Robert Frost MS	Asphalt	113	Quince Orchard HS	Window Replacements
55	Robert Frost MS	Floor Covering	114	Quince Orchard HS	Library Security Gate
56	Robert Frost MS	Line Painting	115	Redland MS	Gas Water Heater
57	Gaithersburg ES	Walk-In-Cooler & Freezer	116	Redland MS	Restroom Repairs
58	Gaithersburg MS	Doors Exterior	117	Judith A. Resnik ES	Playground Equipment
59	Gaithersburg MS	Paint (Interior & Exterior)	118	Judith A. Resnik ES	Concrete Replacement

	Facility	Project Scope		Facility	Project Scope
119	Judith A. Resnik ES	Courtyard Renovation	144	Stedwick ES	Playground Equipment
120	Judith A. Resnik ES	Door Replacement	145	Stephen Knolls School	Playground Equipment
121	Judith A. Resnik ES	PA System	146	Stone Mill ES	Playground Equipment
122	Dr. Sally K. Ride ES	Playground Equipment	147	Stone Mill ES	Floor Covering
123	Dr. Sally K. Ride ES	Pump	148	Strathmore ES	Restroom Repairs
124	Dr. Sally K. Ride ES	Paint (Interior & Exterior)	149	Strathmore ES	PA System
125	Summit Hall ES	Boiler Replacement	150	Takoma Park MS	Restroom Repairs
126	Takoma Park ES	Restroom Repairs	151	Tilden MS	Restroom Repairs
127	Ridgeview MS	Asphalt (Driveway, Parking Lot)	152	Viers Mill ES	Exterior Wall Repairs
128	Ridgeview MS	Line Painting	153	Watkins Mill HS	Auditorium Lighting and Rigging
129	Lois P. Rockwell ES	PA System	154	Watkins Mill HS	Electrical Panels (Concession Stand)
130	Rocky Hill MS	Paint Main Entrance/Canopies	155	Watkins Mill HS	Masonry Wall (Phase 1)
131	Rocky Hill MS	Flooring Locker Room	156	Westover ES	Paint (Ductwork in AP Room)
132	Rolling Terrace ES	Walk-In-Cooler & Freezer	157	Whetstone ES	Restroom Repairs
133	Rosemary Hills ES	Painting (Interior)	158	Whetstone ES	Walk-In-Cooler & Freezer
134	Rosemont ES	Playground Equipment	159	White Oak MS	Line Painting
135	Silver Spring International MS	Exterior Repairs	160	White Oak MS	Masonry Wall
136	Flora M. Singer ES	Emergency Repairs	161	White Oak MS	Stair Treads (Phase 1 of 2)
137	Sligo Creek ES	Masonry Wall Repairs	162	White Oak MS	Tennis Court Renovation
138	Sligo MS	Gym Floor (Main)	163	Walt Whitman HS	Gym Floor
139	South Lake ES	Gas Water Heater	164	Walt Whitman HS	Doors Penthouse
140	South Lake ES	Playground Equipment	165	Earle B. Wood MS	Library Security Gate
141	Springbrook HS	Tennis Court Renovation	166	Woodfield ES	Emergency Generator
142	Stedwick ES	Restroom Repairs	167	Thomas S. Wootton HS	Tennis Court Renovations
143	Stedwick ES	Paint Exterior Wall, Siding & Windows			