

Appendix K

Planned Life-cycle Asset Replacement (PLAR) Projects Completed Summer 2023

	Facility	Project Scope
1	Argyle MS	Floor Covering Replacement
2	John T. Baker MS	Windows and Doors Replacement—Phase 2
3	Benjamin Banneker MS	Operable Wall (both Gyms)
4	Benjamin Banneker MS	Door Replacements (Interior)
5	Benjamin Banneker MS	Asphalt Repaving
6	Lucy V. Barnsley ES	Emergency Generator
7	Belmont ES	Gym Light Fixture Upgrade
8	Belmont ES	Gym Floor Replacement
9	Belmont ES	Basketball Backstops Replacement
10	Belmont ES	Painting (Exterior and Interior)
11	Bethesda Chevy Chase HS	Exterior Wall Repairs and Waterproofing
12	Bethesda ES	Masonry Wall Repairs
13	Montgomery Blair HS	Light Fixture Replacement (Exterior)
14	Montgomery Blair HS	Renovations of Tennis Courts
15	Montgomery Blair HS	Light Fixture Replacements (Compact Florescent)
16	James Hubert Blake HS	Painting (Exterior and Interior)
17	Brookhaven ES	Elevators (2)
18	Cedar Grove ES	Painting (Exterior and Interior)
19	Chevy Chase ES	Painting (Exterior and Interior)
20	Chevy Chase ES	Exterior Wall Repairs and Waterproofing
21	Winston Churchill HS	Tennis Courts Resurfacing
22	Clarksburg HS	Stage Refinishing
23	Clearspring ES	Concrete Repairs
24	Cold Spring ES	Door Replacements(Exterior)
25	Capt. James E. Daly ES	Door Replacements (Exterior)
26	Capt. James E. Daly ES	Water Bottle Filling Station
27	Damascus ES	Walk-in Cooler Box Replacement
28	DuFief ES	Painting (Exterior and Interior)
29	DuFief ES	Gym Light Fixture Upgrade
30	DuFief ES	Basketball Backstops Replacement
31	DuFief ES	Gym Floor Replacement
32	DuFief ES	Exterior Wall Repairs and Waterproofing
33	DuFief ES	Asphalt Repaving
34	Albert Einstein HS	Door Replacements (Interior)
35	William H. Farquhar MS	Tennis Courts Resurfacing
36	Fields Road ES	Window Replacements
37	Forest Oak MS	Painting (Exterior and Interior)
38	Fox Chapel ES	Light Fixture Replacements (Exterior)
39	Gaithersburg HS	Tennis Courts Resurfacing
40	Gaithersburg MS	Concrete Repair
41	Georgian Forest ES	Gym Light Fixture Upgrade
42	Georgian Forest ES	Basketball Backstops Replacement
43	Georgian Forest ES	Gym Floor Refinishing
44	Germantown ES	Masonry Wall Repair
45	Goshen ES	Doors (Exterior)
46	Highland ES	Floor Covering Replacement
47	Highland ES	Sewer Line Repair
48	Highland ES	Door Replacements (Exterior)
49	Highland View ES	Gym Floor Replacement
50	Jackson Road ES	ADA Lift
51	Walter Johnson HS	Replacement of Operable Walls with Curtain Dividers (Gym)
52	Jones Lane ES	Door Replacements (Exterior)
53	John F. Kennedy HS	Running Track Upgrade

	Facility	Project Scope
54	Dr. Martin Luther King Jr. MS	Floor Covering Replacement
55	Lake Seneca ES	Foundation repairs
56	Lake Seneca ES	Paint (Exterior and Interior)
57	Lake Seneca ES	Window Replacements
58	Laytonsville ES	Window Replacements
59	A. Mario Loiederman MS	Carpet Replacement (IMC & Main Office)
60	Thurgood Marshall ES	Floor Covering Replacement
61	S. Christa McAuliffe ES	Floor Covering Replacement
62	Mill Creek Towne ES	Painting (Exterior and Interior)
63	Monocacy ES	Walk-in Cooler Box Replacements
64	New Hampshire Estate ES	Elevator
65	Northwest HS	Walk-in Cooler Box Replacements
66	Oakland Terrace ES	Security System Upgrade
67	Oakview ES	Floor Covering Replacement
68	Olney ES	ADA Lift
69	Rosa M. Parks MS	Light Fixture Replacements (Exterior)
70	Pine Crest ES	Emergency Generator Replacement
71	Poolesville ES	Door Replacements (Exterior)
72	Poolesville HS	Running Track Upgrade
73	Thomas W. Pyle MS	ADA Lift
74	Quince Orchard HS	Door Replacements Exterior (Phase 1)
75	Redland MS	Floor Covering Replacement
76	Ridgeview MS	Painting (Exterior and Interior)
77	Rock Creek Valley ES	Wall Repairs & Waterproofing
78	Rockview ES	Gym Light Fixture Upgrade
79	Rockview ES	Gym Floor Refinishing
80	Losi P. Rockwell ES	Drop Ceiling and light Replacements
81	Rolling Terrace ES	Window Replacements
82	Rosemont ES	Gym Light Fixture Upgrade
83	Sequoyah ES	Gym Light Fixture Upgrade
84	Sequoyah ES	Gym Floor Refinishing
85	Sequoyah ES	Basketball Backstops Replacement
86	Shade Grove MS	Gym Light Fixture Upgrade
87	Springbrook HS	Irrigation System Upgrade
88	Springbrook HS	ADA Lift
89	Springbrook HS	Asphalt Repaving (Phase 1)
90	Stephen Knoll Center	Replacement of Federal Pacific Switchgear Equipment
91	Strathmore ES	Cabinets and Sinks in 16 classrooms
92	Stone Mill ES	PreK Play Equipment Installation
93	Twinbrook ES	Asphalt Repaving
94	Twinbrook ES	Floor Covering Replacement
95	Twinbrook ES	Painting (Exterior and Interior)
96	Waters Landing ES	Elevator
97	Waters Landing ES	Gym Light Fixture Upgrade
98	Waters Landing ES	Gym Floor Refinishing
99	Watkins Mill ES	Window Replacements
100	Watkins Mill ES	PA System Replacement
101	Watkins Mill HS	Door Replacements (Exterior)
102	Watkins Mill HS	Gym Floor Refinishing
103	Westland MS	Gym Floor Refinishing
104	Whetstone ES	Cabinets and Sinks Replacement
105	Whetstone ES	Drop Ceiling and Lights Replacement Phase 2 of 2